

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2023

Submitted Date:

09/26/2023

Document Number:

708901795

FIELD INSPECTION FORMLoc ID 323788 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------|
| , Mustang | | nwelch@vaqueroenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 210809 | WELL | PR | 12/01/2016 | GW | 045-06567 | MOORE 27-42-6S-94W | PR |

General Comment:**CECMC Inspection Report Summary**

On 09/25/2023 at approximately 13:16 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection at MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad.
Location # 323788 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Nest/Roost sites & in close proximity to NSO Habitat area.
Location is approximately 104 yards from the Colorado River & 321 yards from Porcupine Creek.
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Weeds/Undesirable Plant Species on location with a CA date of 10/03/2023
2. Equipment - Meter calibration info not conspicuously posted with a CA date of 10/06/2023
4. Stormwater - Erosion & transport of sediment on location with a CA date of 10/11/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

| Location | | | | |
|--|---|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | BATTERY | | | |
| Comment: | No tank battery | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | 911/888-291-8588 | | | |
| Corrective Action: | | | | Date: _____ |
| Good Housekeeping: | | | | |
| Type | WEEDS | | | |
| Comment: | Weeds/Undesirable Plant Species on location | | | |
| Corrective Action: | Oil & gas locations will be kept free of undesirable plant species. | | | Date: 10/03/2023 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Equipment: | | | | |
| Type: Deadman # & Marked | # 1 | | | corrective date |
| Comment: | Marked | | | |
| Corrective Action: | | | | Date: |
| Type: Bradenhead | # 1 | | | |
| Comment: | No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible. | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | Meter calibration info not conspicuously posted. Door to meter house has a lock on it, unable to check/verify cal card. | | | |
| Corrective Action: | The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times. | | | Date: 10/06/2023 |
| Type: Plunger Lift | # 0 | | | |
| Comment: | Well is not on plunger lift | | | |

| | | | |
|------------------------|----|-------|--|
| Corrective Action: | | Date: | |
| <u>Venting:</u> | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| <u>Flaring:</u> | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | | |
|----------------------|-------------------------------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 210809 | Type: WELL | API Number: 045-06567 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing, well not on plunger lift | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---|
| Other | Fail | | | | | Erosion & transport of sediment on location |
| Compaction | | | | | | |
| | | Compaction | | | | |
| Gravel | | | | | | Sparse to none |
| | | Gravel | | | | Sparse in some areas |

Comment: 1. Erosion & transport of sediment on location

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 10/11/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|----------|------------|
| Please refer to Housekeeping, Equipment & Stormwater for observed compliance issues. | smelserw | 09/26/2023 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 403542547 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265031 |
| 708901796 | Inspection 708901795 Stormwater photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265028 |
| 708901797 | Inspection 708901795 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265029 |