

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2023

Submitted Date:

09/26/2023

Document Number:

708901798

**FIELD INSPECTION FORM**Loc ID 324059 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211601	WELL	PR	08/02/2001	GW	045-07362	BERNKLAU RMV 119-33	PR

**General Comment:****CECMC Inspection Report Summary**

On 09/25/2023 at approximately 11:04 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 119-33 Pad.  
Location # 324059 in Garfield County Colorado.  
Location is within High Priority/Density/Black Bear Habitat areas.  
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Storage of equipment/unused equipment with a CA date of 10/26/2023
2. Equipment - Unmarked deadman with a CA date of 10/10/2023
3. Stormwater - Culvert needs maintenance & Erosion & transport of sediment off location with a CA date of 10/11/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign weathered & cracking but still legible		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Storage of equipment/unused equipment		
Corrective Action:	The storage, placement, or maintenance of equipment, vehicles, trailers, commercial products, Chemicals, drums, totes, Containers, materials, and all other supplies not necessary for use on an Oil and Gas Locations is prohibited.		Date: 10/26/2023
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Barbed wire		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	1 unmarked deadman		
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.	Date:	10/10/2023
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	



Inspected Facilities			
Facility ID: 211601	Type: WELL	API Number: 045-07362	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
Culverts	Fail					Culvert needs maintenance
Compaction						
Ditches						
		Compaction				
Other	Fail					Erosion & transport of sediment off location
Gravel						Sparse to none

Comment: 1. Culvert needs maintenance  
2. Erosion & transport of sediment off location

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 10/11/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Please refer to Housekeeping, Equipment & Stormwater for observed compliance issues.	smelserw	09/26/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403542684	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265359">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265359</a>
708901799	Inspection 708901798 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265357">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265357</a>
708901800	Inspection 708901798 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265358">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265358</a>