

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 16-6 (RD16) Pad

Location #: 334611



Photo # 2474 From entrance to location



Photo # 2475 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 16-6 (RD16) Pad

Location #: 334611




Photo # 2476 Location



Photo # 2477 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 16-6 (RD16) Pad

Location #: 334611



Photo # 2478 Location



Photo # 2479 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 16-6 (RD16) Pad

Location #: 334611



Photo # 2480 Location



Photo # 2481 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 16-6 (RD16) Pad

Location #: 334611



Photo # 2482 Holes in containment liner/liner needs maintenance




Photo # 2483 Holes in containment liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 16-6 (RD16) Pad

Location #: 334611



Photo # 2484 Holes in containment liner/liner needs maintenance



Photo # 2485 Holes in containment liner/liner needs maintenance