

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2023

Submitted Date:

10/20/2023

Document Number:

701007508**FIELD INSPECTION FORM**Loc ID 303377 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 97120Name of Operator: WISE* WAYNE LAddress: P O BOX 5116City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wise, Wayne		wwise@peakviewenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253011	WELL	PR	12/01/2020	GW	125-06888	ALICE WELP 1-10	PR

General Comment:[P&A Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Trail through CRP		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Wire panels around wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried by meter shed		
Corrective Action:	Remove equipment and begin final reclamation process		Date: 11/20/2023
Type: Gas Meter Run	# 1		
Comment:	Meter run is 1245' southwest of wellhead next to Allison 1-9 meter shed		
Corrective Action:	Remove equipment and begin final reclamation process		Date: 11/20/2023

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 253011 Type: WELL API Number: 125-06888 Status: PR Insp. Status: PR**Cement**Cement ContractorContractor Name: Excel Well Service

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 2200/1750/456Cement Volume (sx): 96 SXS

Good Return During Job: _____

Cement Type: NeatComment:

LOG TECH WIRELINE, EXCEL WELL SERVICE. MIRU LOGTECH, RIH W/CIPB TO 2200', BALE DUMP 2 SXS ON TOP. RIH W/CIBP TO 1750', BALE DUMP 2 SXS CMT ON TOP. RIH W/GUN, PERF @ 456'. MIRU EXCEL, PUMP PUMP 37BBLs WATER TO BREAK CIRC, PUMP 96 SXS W/CMT TO SFC.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403567635	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6292606