

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2023

Submitted Date:

10/27/2023

Document Number:

709100140

FIELD INSPECTION FORM

 Loc ID 312244 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 55030Name of Operator: MCCARTNEY ENGINEERING LLCAddress: 4251 KIPLING ST STE 575City: WHEAT RIDGE State: CO Zip: 80033**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments5 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
McCartney, Ron		ron@mccartneyengineering.com	
Krystal Heibel		krystal.heibel@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
McCartney, Jack	303-830-7208	jack@mccartneyengineering.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219792	WELL	PR	07/01/2018	OW	075-07226	RICE 4	EI

General Comment:

On October 18, 2023, ECMC Environmental Unit Staff Krystal Heibel and Kyle Waggoner inspected the Rice #4 location (Location ID: 312244). API# 05-075-07226

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign on location does not contain required equipment, and there is no sign posted at wellhead with the required information.		
Corrective Action:	Install sign to comply with Rule 605.a. and Rule 605.d.		Date: 11/28/2023
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:	Trash (metal piping on site and tubing located within grass) located on site.		
Corrective Action:	Comply with Rule 606		Date: 11/13/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment location on site within the metal shed.		
Corrective Action:	Comply with Rule 606		Date: 11/13/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	Hydrocarbon impacted soils located throughout the site: near the wellhead, next to the pump jack unit, behind the metal shed, and within the metal shed. See photo documentation.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 11/28/2023
In Containment: No			
Comment:	<input style="width: 100%;" type="text" value="A paint bucket full of hydrocarbons located on site next to the pump jack unit."/>		
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	#		corrective date
Comment:	Wildlife protections devices not adequate. Unauthorized discharge of E&P Waste from multiple pipe openings on location. No wildlife protections observed for poly tank. See photos attached for reference.		
Corrective Action:	Install or repair wildlife protection equipment. Prevent any unauthorized discharge.		Date: 11/06/2023
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 219792 Type: WELL API Number: 075-07226 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403575489	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300804
709100141	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300776