

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2023

Submitted Date:

11/17/2023

Document Number:

701007628

**FIELD INSPECTION FORM**Loc ID 321871 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 34105

Name of Operator: GILBERT-STEWART OPERATING LLC

Address: 1801 BROADWAY STE 200

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gilbert, Kent	303-534-1686	kgoil@msn.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208289	WELL	TA	01/01/2020	OW	017-07224	AKERS 2	PA

**General Comment:**

P&amp;A Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Trail through farm ground		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by cathodic rectifier		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 0		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier		
Corrective Action:	Remove equipment from location to begin final reclamation process	Date:	12/14/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 208289 Type: WELL API Number: 017-07224 Status: TA Insp. Status: PA**Cement**Cement ContractorContractor Name: HP Oilfield Service

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 3674/2345/1600/500Cement Volume (sx): 300 SXS

Good Return During Job: \_\_\_\_\_

Cement Type: Class AComment:

PEAK WIRELINE, HP OILFIELD SERVICES, EASTERN COLORADO WELL SERVICE. MIRU PEAK, RIH W/CICR SET @ 3674'. MIRU ECWS, RIH W/TBG, STING INTO CICR. MIRU HP, PUMP 45 SXS THRU CICR W/5 SXS ON TOP. MIRU ECWS, POOH W/TBG. MIRU PEAK, RIH W/GUN, PERF @ 2395'. RIH W/CICR, WIRELINE SET @ 2345'. MIRU ECWS, RIH W/TBG STING INTO CICR. MIRU HP, PUMP 45 SXS THRU W/5 SXS ON TOP. MIRU ECWS, POOH W/TBG. MIRU PEAK, RIH W/GUN, PERF @ 1650' AND 500'. RIH W/CICR TO 1600'. MIRU ECWS, RIH W/TBG, STING INTO CICR. MIRU HP, PUMP 45 SXS THRU W/5 SXS ON TOP. MIRU ECWS, POOH W/TBG TO 1000'. MIRU HP, PUMP 30BBLS WATER TO FLUSH CSG. MIRU ECWS, POOH W/TBG. MIRU HP, PUMP 100 SXS CMT (LEAD) 50 SXS (TAIL) W/CaCl. SHUT IN WELL.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403600022	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327152">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327152</a>
701007638	Location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327110">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327110</a>