

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2023

Submitted Date:

11/17/2023

Document Number:

701007629**FIELD INSPECTION FORM**Loc ID 324857 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 61250Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Akers, Tracy	719-342-1813	takers@mulldrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213237	WELL	SI	02/01/2023	GW	061-06599	PECK 1	PA

General Comment:[P&A Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt road along edge of farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier on REA pole		
Corrective Action:	Remove from location to begin final reclamation process		Date: 12/15/2023
Type: Horizontal Heated Separator	# 1		
Comment:	HHS on east side of water tank		
Corrective Action:	Remove from location to begin final reclamation process		Date: 12/15/2023
Type: Gas Meter Run	# 1		
Comment:	Meter run south of separator		
Corrective Action:	Remove from location to begin final reclamation process		Date: 12/15/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	Open Top		38.528740,-103.042080
Comment:	Fiberglass open top water tank				
Corrective Action:	Remove from location to begin final reclamation process				Date: 12/15/2023

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 213237 Type: WELL API Number: 061-06599 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: HP Oilfield Services

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 1587/1279/630Cement Volume (sx): 325 SXSGood Return During Job: YESCement Type: Class A

Comment: HALDE WATER, CODELL WELL SERVICE, PEAK WIRELINE, HP OILFIELD SERVICE. MIRU PEAK, RIH W/GUN, PERF @ 1587'. MIRU HP, PUMP 12 SXS CMT (W/CaCl) INTO PERFS AND LEAVE 38 SXS (W/CaCl) CMT IN CSG. MIRU CODELL, POOH W/TBG. WOC 1 HR. MIRU PEAK, RIH AND TAG CMT @ 1430'. RIH W/GUN, PERF @ 1279'. MIRU CODELL, RIH W/TBG. MIRU HP, PUMP 12 SXS CMT (W/CaCl) INTO PERFS AND LEAVE 38 SXS (W/CaCl) CMT IN CSG. MIRU CODELL, POOH W/TBG. MIRU PEAK, RIH W/GUN, PERF @ 630'. MIRU HP, PUMP 225 SXS W/CMT TO SFC.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: [Location and access is farmed over](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403600035	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6327170