

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/06/2023

Submitted Date:

12/06/2023

Document Number:

696305468

FIELD INSPECTION FORM

Loc ID 435952 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 23 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435953	WELL	SI	07/01/2023	OW	123-38878	State Antelope D14-X44-2HNC	SI
435954	WELL	SI	08/01/2023	OW	123-38879	State Antelope 14-44-2HNC	SI
435955	WELL	SI	07/01/2023	OW	123-38880	State Antelope D-X-2HNC	SI
449330	WELL	PR	01/16/2019	OW	123-44262	State Antelope J24-2-14XRLNB	PR
449331	WELL	PR	02/06/2019	OW	123-44263	State Antelope 14-2-14XRLNB	PR
449332	WELL	PR	01/11/2019	OW	123-44264	State Antelope E-2-14XRLNB	PR
454853	WELL	SI	07/01/2023	OW	123-46747	State Antelope 24-2-14XRLNB	SI

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank 220761 - Capacity Label Tanks 1338 and 1339 - NFPA Labels		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	1" Riser at East Side of Tanks is disconnected flowline risers not OOSLAT.		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.		Date: 12/22/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Other	# 1		
Comment:	Line Heater		
Corrective Action:			Date:

Type: Ancillary equipment	# 1		
Comment:	Automation and Electrical Equipment		
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:	25		
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 15		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 6		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	Instrumental Air Units		
Corrective Action:			Date:
Type: VRT	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:	22		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBLS
Other (Type)	

Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shares berm with the Crude Oil Tanks						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST			
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shares berm with the Crude Oil Tanks						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	12	400 BBLs	STEEL AST		40.424130,-104.296940	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berm						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						

Corrective Action:

Date:

Inspected Facilities				
Facility ID: 435953	Type: WELL	API Number: 123-38878	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: <input style="width: 80%;" type="text" value="SI"/>				
Corrective Action: <input style="width: 80%;" type="text"/>				Date: <input style="width: 20%;" type="text"/>
Facility ID: 435954	Type: WELL	API Number: 123-38879	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: <input style="width: 80%;" type="text" value="SI"/>				
Corrective Action: <input style="width: 80%;" type="text"/>				Date: <input style="width: 20%;" type="text"/>
Facility ID: 435955	Type: WELL	API Number: 123-38880	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: <input style="width: 80%;" type="text" value="SI"/>				
Corrective Action: <input style="width: 80%;" type="text"/>				Date: <input style="width: 20%;" type="text"/>
Facility ID: 449330	Type: WELL	API Number: 123-44262	Status: PR	Insp. Status: PR
Producing Well				
Comment: <input style="width: 80%;" type="text" value="PR"/>				
Corrective Action: <input style="width: 80%;" type="text"/>				Date: <input style="width: 20%;" type="text"/>
Facility ID: 449331	Type: WELL	API Number: 123-44263	Status: PR	Insp. Status: PR
Producing Well				
Comment: <input style="width: 80%;" type="text" value="PR"/>				
Corrective Action: <input style="width: 80%;" type="text"/>				Date: <input style="width: 20%;" type="text"/>
Facility ID: 449332	Type: WELL	API Number: 123-44264	Status: PR	Insp. Status: PR
Producing Well				
Comment: <input style="width: 80%;" type="text" value="PR"/>				
Corrective Action: <input style="width: 80%;" type="text"/>				Date: <input style="width: 20%;" type="text"/>
Facility ID: 454853	Type: WELL	API Number: 123-46747	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: <input style="width: 80%;" type="text" value="SI"/>				
Corrective Action: <input style="width: 80%;" type="text"/>				Date: <input style="width: 20%;" type="text"/>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Tank Labels. 1" Riser at Tanks not OOSLAT	petrie	12/06/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403616955	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347878
696305470	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347816