

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2023

Submitted Date:

12/06/2023

Document Number:

709400662

**FIELD INSPECTION FORM**

Loc ID: 320342      Inspector Name: WOLD, REED      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Operator Information:**  
OGCC Operator Number: 10395  
Name of Operator: GOODWIN ENERGY MANAGEMENT LLC  
Address: 740 S OGDEN STREET  
City: DENVER      State: CO      Zip: 80209

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
3 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		scottgoodwinjr@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203506	WELL	PR	08/11/2010	OW	001-09066	SATTERFIELD 1 (OWP)	RI
320342	LOCATION	AC			-	SATTERFIELD-61S64W 27SWNW	RI

**General Comment:**  
This is an interim and stormwater inspection for wells and associated tank battery on site. No corrective actions observed on previous inspection.  
Corrective actions observed on current locaiton include weeds (kochia) on site, Stormwater erosion on tank battery pad.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

WEEDS

Comment:

Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands.

Corrective Action:

Comply with Rule 606.c. The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date the location was observed out of compliance.

Date: 11/14/2023

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 203506 Type: WELL API Number: 001-09066 Status: PR Insp. Status: RI

Facility ID: 320342 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater erosion on site, sediment is leaving site in to adjacent cropland.](#)

Corrective Action: **Compy with rule 1002.f. Stormwater Management. The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date the location was observed out of compliance.**

Date: 11/14/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403616904	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347845">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347845</a>
709400663	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347827">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347827</a>