

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/06/2023

Submitted Date:

12/06/2023

Document Number:

713300360

FIELD INSPECTION FORMLoc ID 318383 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
,		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241196	WELL	SI	11/01/2021	GW	123-08984	UPRR 43 PAN AM I 25	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	roll of 3" poly		
Corrective Action:	Comply with rule 606	Date:	01/08/2024
Type	UNUSED EQUIPMENT		
Comment:	concrete support pad for pumping unit		
Corrective Action:	Comply with 606	Date:	01/08/2024

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	electrical disconnect panels		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 241196 Type: WELL API Number: 123-08984 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: Defined inactive 10-31-2021Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 04/25/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Wednesday, 12-6-2023 at approximately 13:00, I, Inspector Michael Kester, conducted an on-site inspection.</p> <p>Location: UPRR 43 Pan Am I # 25</p> <p>Operator: KPK</p> <p>API#: 123-08984</p> <p>County: Weld</p> <p>While there, I observed well site with pumping unit with production equipment.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment, Rule 606, corrective action date, 1-8-2024, photo 3 & 4</p> <p>Weather conditions: sunny and dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC</p> <p>This is a continuing education inspection</p>	kesterm	12/06/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403617028	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347982
713300361	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6347960