

Inspection Photos

Loc: 322215

Operator: JAVERNICK OIL

Inspection Date: 12/12/2023



Inspection Photos



Photo 1. Facing north along the access road. A recent storm event has created an erosion gully along the roadside which needs to be repaired.



Inspection Photos



Photo 2. Facing back south toward the erosion gully along the roadside which needs to be repaired. A 4.5 ft. shovel shows depth of erosion.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 322215 | Date: 12/12/2023

Inspection Photos



Photo 3. The culvert at this drainage crossing has filled in with sediment and debris and must be cleaned out.



Inspection Photos



Photo 4. Facing northeast toward the wellsite. This area near the well will need to be stabilized with vegetation. There was marks in the soil that may have been recently seeded.



Inspection Photos



Photo 5. Facing toward the embankment. This area needs to be seeded for stabilization of the embankment or other BMP may be utilized. Shrubs in the area that are easily established include Rubber rabbitbrush and Four wing salt brush.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 322215 | Date: 12/12/2023

Inspection Photos



Photo 6. There is a black plastic pipe that is bent and an audible leak was heard from this area.



Inspection Photos



Photo 7. Facing southeast toward the tank battery.

