

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757



Photo 1 – Pumping Units



Photo 2 – 6-62-23-0164CDH Pumping Unit – Tumbleweeds and Container Label

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757



Photo 3 – 2” Riser West of Pumping Units not OOSLAT



Photo 4 – 2” Riser West of Pumping Units not OOSLAT

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757




Photo 5 – 1" Riser at VRU not OOSLAT – Stained Soil



Photo 6 – Separators

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757



Photo 7 – Separator and Heater Treater



Photo 8 – 2" Buried Riser not OOSLAT

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757




Photo 9 – 2" Buried Riser not OOSLAT




Photo 10 – 2" Buried Riser and 1" Riser not OOSLAT

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757



Photo 11 – 2" Buried Riser not OOSLAT



Photo 12 – 2" Buried Risers not OOSLAT

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757




Photo 13 – 2" Buried Riser not OOSLAT



Photo 14 – Heater Treater and VRTs

Location ID: 432757



Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757



Photo 17 – NFPA, Content and Capacity Labels missing on SE Tank



Photo 18 – ECDs