

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Tumbleweed Debris at Wellhead; see photos		
Corrective Action:	Comply with 606	Date:	12/29/2023
Type	STORAGE OF SUPL		
Comment:	Unused Pipe at Well Site; see photos		
Corrective Action:	Comply with 606	Date:	12/29/2023

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	TA Wellhead		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
------	--	--	--

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 422226 Type: WELL API Number: 123-33198 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA - Since 05.06.2020. MIT 04.20.2020
Form 6A 403226263 with Plug Date 12.31.2027

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
Routine Field Inspection. Tumbleweed Debris at Wellhead. Unused Pipe at Wellsite	petrie	12/13/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403624626	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6355715
696305497	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6355680