



Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

Photo #1, Sign at Facility





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #2 Tank Battery. The tank battery was inspected for fencing and general observation.**





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #3 Tank Battery. The tank battery was inspected for fencing and general observation.**





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #4 looking north at Pit complex.**





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #5 looking north at pit facility and cement vault on right.**



Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #6 Pit inside of fenced complex. Looking northeast across the pit. Note: visible hydrocarbon on pit.**





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #7 looking across the pit to the northwest. Note: visible hydrocarbon on pit.**





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #8 Looking across pit. Fence seen at left of photo is the western side of pit.**



Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #9. Close up of the western portion of fence. Note: wildlife tracks crossing under the fence. The track Path went from the main access gate (on east side) across the access drive inside the facility and under the fence seen here.**





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #10 Photo is attempting to show the bottom of the west side fence. The fence is curled up allowing access (or egress) through fence.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #11 Photo of Pit. Note: black hydrocarbon.**





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

Photo #12 photo of former discharge from pit. Discharge point to seeping springs gulch is to left of photo.



Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #13 Piping in foreground is same piping that is observable in Photo #12**





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #14 Photo below discharge to Seeping Springs Gulch. Note: netting used for fencing.**





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #15 Netting used as fencing at discharge to seeping springs gulch.**



Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #16 Close up of fencing at discharge. Old netting used as fence.**





Inspection Photos  
REM #28246  
Facility #116587  
Inspection  
Date:12/21/2023

All Photos taken  
by ECMC staff, Kris  
Neidel

**Photo #17 Close up of fencing at discharge. Old netting used as fence.**

