

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/20/2023

Submitted Date:

01/05/2024

Document Number:

701007826

FIELD INSPECTION FORM

Loc ID 321617 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 61650
 Name of Operator: MURFIN DRILLING COMPANY INC
 Address: 250 N WATER ST STE 300
 City: WICHITA State: KS Zip: 67202

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|----------------|-------------------------|---------|
| Goodrich, Cristina | (316) 858-8664 | cgoodrich@murfininc.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 207529 | WELL | TA | 05/01/2022 | OW | 017-06464 | LOWE 8-12 | PA |

General Comment:

[Routine Inspection](#)

Location

| | | | |
|--------------------|-------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt road through farm ground | | |
| Corrective Action: | | Date: | |

Overall Good:

| | |
|---------------------------|---|
| Emergency Contact Number: | |
| Comment: | <input style="width: 100%;" type="text"/> |
| Corrective Action: | <input style="width: 100%;" type="text"/> |
| Date: | _____ |

| | | | |
|---------------------------|---|--|------------------|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Pipe, chemical tanks and debris laying around | | |
| Corrective Action: | Comply with Rule 606 | | Date: 01/20/2024 |

Overall Good:

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|---------------------------|--|--|------------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Cathodic rectifier still on location | | |
| Corrective Action: | Remove equipment and begin final reclamation process | | Date: 01/27/2024 |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | Remove equipment and begin final reclamation process | | Date: 01/27/2024 |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 207529 Type: WELL API Number: 017-06464 Status: TA Insp. Status: PA

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | | | | | |

Comment: Location is grassed over

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403646125 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6382812 |
| 701007908 | location photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6382788 |