

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/25/2024

Submitted Date:

01/25/2024

Document Number:

695109072

FIELD INSPECTION FORM

Loc ID 322265 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 44390
Name of Operator: JAVERNICK OIL
Address: 3040 E MAIN
City: CANON CITY State: CO Zip: 81212

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|---------------------------|----------------------------------|---------------------------------|
| | | dnr_cogccengineering@state.co.us | |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Javernick, James | 719-275-3040/719-671-3787 | javernick1@gmail.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 210087 | WELL | PR | 04/22/2003 | OW | 043-40024 | ROB HIAWATHA 2 | PR |

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: CATTLE PANEL

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

0

Comment: PHOTO 5: Bradenhead inaccessible or not visible.

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). THIS IS THE 3RD NOTICE, IMMEDIATE ACTION IS REQUIRED.

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 100 BBLS | STEEL AST | | 38.326280,-105.124360 |

Comment: PHOTO 6: GUAGE HATCH HAS NO LATCH AND IS LEAKING (SEE ATTACHED FLIR VIDEO) ALSO 2' RISER ON CRUDE OIL TANK DOES NOT APPEAR TO HAVE PRESSURE RELIEF VALVE.

Corrective Action: Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9). THIS IS THE 2ND NOTICE IMMEDIATE ACTION IS REQUIRED.

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: <input type="text"/> | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | NO | | |
| Comment: | FLIR CAMERA INDICATES THAT THERE IS STEADY GAS VENTING FROM TOP OF CRUDE OIL TANK, THE TBG/CSG ANNULUS AND THE PRODUCTION CSG/SURFACE CSG ANNULUS. | | |
| Corrective Action: | Close well to atmosphere as directed by Rule 434.b.(1) THIS IS THE 3RD NOTICE, IMMEDIATE ACTION IS REQUIRED. | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 210087 Type: WELL API Number: 043-40024 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/23/2022 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

NOTE THAT BRADENHEAD TEST HAS BEEN SUBMITTED HOWEVER THERE APPEARS TO BE NO BRADENHEAD ON WELLHEAD ASSEMBLY.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| THIS IS A FOLLOW UP TO INSP. DOC #'S 695106885 & 707900384, CA'S HAVE NOT BEEN ADDRESS, IMMEDIATE ACTION IS REQUIRED AN FIRR MUST BE FILED WHEN CA'S HAVE BEEN ADDRESSED. | beardslt | 01/25/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403670610 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6411728 |
| 695109073 | INSP. PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6411702 |
| 695109074 | FLIR VIDEO | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6411703 |