

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2024

Submitted Date:

01/30/2024

Document Number:

710100137**FIELD INSPECTION FORM**Loc ID 318508 Inspector Name: Anderson, Laurel On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hamilton, Greg		Gregory_Hamilton@oxy.com	Oxy Environmental
,		ECMCInspections@Oxy.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	
Brown, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241436	WELL	PR	08/01/2023	GW	123-09225	PACE-CONNELLY 3	EI
419141	WELL	SI	07/01/2021	OW	123-32148	WILDFLOWER 16-27	EI
419150	WELL	SI	07/01/2021	OW	123-32154	WILDFLOWER 37-27	EI
419153	WELL	PR	05/01/2022	OW	123-32155	WILDFLOWER 15-27	EI
419197	WELL	PR	01/01/2020	OW	123-32177	WILDFLOWER 23-27	EI

General Comment:

This is an ECMC environmental inspection performed on January 26th, 2024. ECMC inspected the following Kerr McGee (Operator) wellheads:

123-32148 WILDFLOWER 16-27

123-32154 WILDFLOWER 37-27

123-32155 WILDFLOWER 15-27

123-32177 WILDFLOWER 23-27

During the inspection ECMC EPS noted a leak at the WILDFLOWER 15-27 and stained soil below.

Photos attached to document site conditions.

No Operator personnel were present at the time of inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
PW/CO	WELLHEAD	<= 1 bbl		
Comment:	During the inspection ECMC EPS noted a leak at the WILDFLOWER 15-27 and stained soil below.			
Corrective Action:	Operator shall immediately control and contain spills/releases and clean up per Rule 912.a. Note: For any spills that do not meet the reporting requirements of Rule 912.b.; Operator shall provide documentation of the cleanup efforts (photo documentation) to the Director per Rule 912.a.(5) - Operator may submit documentation via FIRR. Additionally, Operator shall properly handle, transport and dispose of E&P waste in accordance with 905 Series Rules.			Date: 02/06/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	241436	Type:	WELL	API Number:	123-09225	Status:	PR	Insp. Status:	EI
Facility ID:	419141	Type:	WELL	API Number:	123-32148	Status:	SI	Insp. Status:	EI
Facility ID:	419150	Type:	WELL	API Number:	123-32154	Status:	SI	Insp. Status:	EI
Facility ID:	419153	Type:	WELL	API Number:	123-32155	Status:	PR	Insp. Status:	EI
Facility ID:	419197	Type:	WELL	API Number:	123-32177	Status:	PR	Insp. Status:	EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403670292	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6411432
710100138	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6411413