



**Location**

Overall Good:

Emergency Contact Number: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds unmanaged on location		
Corrective Action:	Comply with rule 606	Date:	02/06/2024

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent			
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 242821 Type: WELL API Number: 123-10612 Status: PR Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/12/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On 1/30/24 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Jordan, Ivar 1                      Company Name- KPK                      API- 05-123-10612                      In Weld County Colorado.                      While there, I observed SI well                      During this inspection the following possible compliance issues were observed:                      Weeds. Rule 606. 2/6/24                      A follow up on this site inspection needs to be conducted to ensure the compliance issues                      have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p>	medinaj	01/30/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403675781	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417414">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417414</a>
699505328	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417363">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417363</a>