

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2024

Submitted Date:

02/02/2024

Document Number:

708301620**FIELD INSPECTION FORM**

Loc ID 335656	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 9 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278559	WELL	PR	12/01/2018	GW	045-10895	N.PARACHUTE WF16D O23 596	PR
278560	WELL	PR	12/01/2018	GW	045-10894	N. PARACHUTE WF16B O23 596	PR
278561	WELL	SI	05/01/2023	GW	045-10893	N.PARACHUTE WF13D O23 596	SI
278563	WELL	PR	12/01/2018	GW	045-10892	N.PARACHUTE WF13B O23 596	PR
278568	WELL	PR	12/01/2018	GW	045-10891	N.PARACHUTE WF12B O23 596	PR
278572	WELL	PR	12/01/2018	GW	045-10890	N.PARACHUTE WF10D O23 596	PR
278575	WELL	PR	12/01/2018	GW	045-10889	N.PARACHUTE WF09D O23 596	PR
278577	WELL	PR	12/01/2018	GW	045-10888	N.PARACHUTE WF04B O23 596	PR

General Comment:

COGCC Inspection Report Summary

On 1/30/2024 at approximately 13:25, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/23SWSE at Location ID #335656 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) No wellhead signs posted

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	No wellhead signs posted.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	03/03/2024
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 285-2615

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas meters/lift protected by concrete barriers and pipe rails.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		

Comment:	Gas lift		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	278559	Type:	WELL	API Number:	045-10895	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	278560	Type:	WELL	API Number:	045-10894	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	278561	Type:	WELL	API Number:	045-10893	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:									
Corrective Action:						Date:			
Facility ID:	278563	Type:	WELL	API Number:	045-10892	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	278568	Type:	WELL	API Number:	045-10891	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	278572	Type:	WELL	API Number:	045-10890	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	278575	Type:	WELL	API Number:	045-10889	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	278577	Type:	WELL	API Number:	045-10888	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:			
Corrective Action:			Date: <div></div>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
				Material Handling And Spill Prevention		Chemical tank in secondary containment
		Sediment Traps				
		Compaction				
		Check Dams				
		Rip Rap				
		Ditches				
Compaction						
		Gravel				
Gravel						
		Berms				

Comment: [Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403676013	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417734
708301621	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417733