

Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate	
Comment: Rule 603.o.(1): Maintained berms around tank(s).					
Corrective Action: Corrective Action Date 4/5/2024. See attached photo #2				Date:	<u>04/05/2024</u>
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.837398,-104.296867
Comment: Rule 905e: Stained soil. Control and contain spills/releases and clean up per Rule 905e.					
Corrective Action: Corrective Action Date 3/22/2024 to remove stained soil. See attached photo #3				Date:	<u>03/22/2024</u>

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate	
Comment: Rule 603.o.(1): Maintained berms around tank(s). Corrective Action Date 4/5/2024. See attached photo #2					
Corrective Action: Corrective Action Date 4/5/2024. See attached photo #2				Date:	<u>04/05/2024</u>

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
001-06554		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 201151 Type: WELL API Number: 001-06554 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary On Monday February 26th, 2024 at approximately 11:52am. I, Inspector Chane Finkenbinder, conducted an on-site follow-up inspection of doc #700901847. Operator: RENEGADE OIL & GAS Location name: UPRR HABEL 1-35 API # 001-06554 Location ID #: 319728 County: Adams While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: Rule 905e: Stained soil. Control and contain spills/releases and clean up per Rule 905e. Corrective Action Date 3/22/2024 to remove stained soil. See attached photo #3 Rule 603.o.(1): Maintained berms around tank(s). Corrective Action Date 45/5/2024. See attached photo #2 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	03/05/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403708788	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6454384
700901989	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6454380