

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/29/2024

Submitted Date:

03/04/2024

Document Number:

710100160

FIELD INSPECTION FORM

Loc ID 318360 Inspector Name: Anderson, Laurel On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Kari		kari.oakman@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections
Hamilton, Greg		Gregory_Hamilton@oxy.com	Oxy Environmental
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453926	TANK BATTERY	AC	02/02/2018		-	Ditlev-Simonsen GU 1& GU2 battery	EI
483688	SPILL OR RELEASE	CL	01/06/2023		-	Ditlev Simonsen GU 2 O SA	EI
483689	SPILL OR RELEASE	CL	01/09/2023		-	Ditlev Simonsen GU 1 flowline	EI

General Comment:

On February 29, 2024, ECMC EPS Laurel Anderson performed an environmental inspection of the following:
Kerr McGee (Operator) Remediation Project #25682
DITLEV-SIMONSEN GAS UNIT-62N67W31NWSW - Location ID #318360
Ditlev Simonsen GU 2 O SA Release - Spill ID #483688
Date of Discovery: 1/6/2023 (CL)
Ditlev Simonsen GU 1 flowline Release - Spill ID 483689
Date of Discovery: 1/9/2023 (CL)

Any corrective actions from previous inspections that have not been addressed are still applicable.
Photos attached to document site conditions at the time of inspection.
The former tank battery and historic releases are located within the Town of Frederick.

Operator personnel were on location at the time of inspection. ECMC discussed the status of ongoing remediation with Operator personnel and signed the JSA upon arrival. Operator crews were observed direct loading impacted soil into a line of dump trucks for offsite disposal (12 trucks were being ran continuously at the time of inspection). One excavator on location was dedicated to removal and direct loading of impacted soil and second excavator on location was dedicated to backfilling. Clean soil and sand are being stockpiled on location for backfill. Sand is being used to backfill the saturated/smear zone and clean fill dirt/top soil is being used to backfill the smear/vadose zone. Groundwater was observed at ~10' bgs.

Operator is behind on quarterly reporting for Remediation Project #25682.
A Warning Letter (Doc #403695219) has been issued for Operator's late Form 27 Supplementals.

Location

Overall Good:

Emergency Contact Number:

Comment: Adequate.

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: Open excavation has cattle fencing installed and warning signage. Portions of the fencing removed for ongoing work are stored on location and reinstalled when work is not being conducted. JSA/Sign-In required upon entrance to location.

Corrective Action:

Date:

Equipment:

corrective date

Type: #

Comment: Equipment has been removed.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 453926 Type: TANK API Number: - Status: AC Insp. Status: EI

Facility ID: 483688 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Facility ID: 483689 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Operator is behind on quarterly reporting for Remediation Project #25682. Operator shall submit a Supplemental Form 27 as soon as possible. See Warning Letter (Doc #403695219).

Operator is 179 days past due on quarterly reporting as of March 4, 2024.

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Pass			No trackout observed.
Comment: Clean topsoil/backfill stockpiles were observed on location with no BMPs. Operator personnel were observed actively backfilling a portion of the open excavation.						Date: 03/18/2024
Corrective Action: Operator shall Manage stockpiles in compliance with Rule 1002.f.(2).						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403707712	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6453395
710100161	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6453393