

**Dugan Production Co Operator #25250  
Tiffany #1 API# 05-067-06498  
Follow Up Inspection #674601361**

Existing well sign and operator emergency contact number.



Open top tank where spill was observed; No stained soils observed; New earthen berm in place; Wildlife screen repaired; New tank signage.



New produced water tank signage installed at facility near dehydrator.



45 bbl open top tank re-leveled;  
maintenance performed on berm and  
liner; unused parts/ trash cleaned up.



Compressor lube oil container  
labeled; Fluid removed from  
containment.



Wildlife screen in place over lube oil  
drum containment.



Compressor skid cleaned; free of oil;  
No evidence of stained soils observed  
around equipment.



General housekeeping performed;  
Weeds removed from around (fired)  
equipment; Unused equipment and  
trash removed from well site.



Fuel containers have been removed  
from under equipment; Paint peeling  
from and rust forming on Dehydrator



View of wellhead; Weeds have been removed from area.



Gate on well site access road has been removed/ secured.



Unpainted and rusting equipment;  
Horizontal heated separator.

