

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/22/2015

Document Number:

682400168

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	443694	443694	Binschus, Chris	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	ALL INSPECTIONS

Compliance Summary:QtrQtr: SESW Sec: 10 Twp: 4N Range: 67W**Inspector Comment:**This is a constuction inspection.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
443667	WELL	XX	10/22/2015		123-42322	Spaur 10T-201	XX	<input checked="" type="checkbox"/>
443668	WELL	XX	10/22/2015		123-42323	Spaur 10Q-241	XX	<input checked="" type="checkbox"/>
443669	WELL	XX	10/22/2015		123-42324	Spaur 10i-201	XX	<input checked="" type="checkbox"/>
443670	WELL	XX	10/22/2015		123-42325	Spaur 10Y-241	XX	<input checked="" type="checkbox"/>
443671	WELL	XX	10/22/2015		123-42326	Spaur 10Q-401	XX	<input checked="" type="checkbox"/>
443672	WELL	XX	10/22/2015		123-42327	Spaur 10L-241	XX	<input checked="" type="checkbox"/>
443673	WELL	XX	10/22/2015		123-42328	Spaur 10i-321	XX	<input checked="" type="checkbox"/>
443674	WELL	XX	10/22/2015		123-42329	Spaur 10L-321	XX	<input checked="" type="checkbox"/>
443675	WELL	XX	10/22/2015		123-42330	Spaur 10L-421	XX	<input checked="" type="checkbox"/>
443677	WELL	XX	10/22/2015		123-42331	Spaur 10L-301	XX	<input checked="" type="checkbox"/>
443679	WELL	XX	10/22/2015		123-42332	Spaur 10Q-321	XX	<input checked="" type="checkbox"/>
443680	WELL	XX	10/22/2015		123-42333	Spaur 10L-201	XX	<input checked="" type="checkbox"/>
443683	WELL	XX	10/22/2015		123-42334	Spaur 10T-321	XX	<input checked="" type="checkbox"/>
443684	WELL	XX	10/22/2015		123-42335	Spaur 10T-241	XX	<input checked="" type="checkbox"/>
443685	WELL	XX	10/22/2015		123-42336	Spaur 10T-301	XX	<input checked="" type="checkbox"/>
443687	WELL	XX	10/22/2015		123-42337	Spaur 10T-421	XX	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: Binschus, Chris

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>16</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: <u>16</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>14</u>	Oil Tanks: <u>32</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	_____
--------	-------

Comment	_____
---------	-------

Flaring:

Type	Satisfactory/Action Required
------	------------------------------

Comment:	_____
----------	-------

Corrective Action:	_____	Correct Action Date:	_____
--------------------	-------	----------------------	-------

Predrill

Location ID: 443694

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: SATISFACTORY

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Data retrieval failed for the subreport 'Subreport1' located at: \\10.12.100.15\cFormReports\Insp\InspCOA.rdl. Please check t

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

Data retrieval failed for the subreport 'Subreport2' located at: \\10.12.100.15\cFormReports\Insp\InspBMP.rdl. Please check t

S/AR: _____ Comment: _____

CA: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
DITCHES	No		

S/A/V: ACTION
REQUIRED

Corrective Action: Need to install Stormwater BMPs prior to construction Date: 12/24/2015

Comments: Erosion BMPs: Need to install Stormwater BMPs by the end of business day of 12/24/2015.

Other BMPs: _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 443667 Type: WELL API Number: 123-42322 Status: XX Insp. Status: XX

Facility ID: 443668 Type: WELL API Number: 123-42323 Status: XX Insp. Status: XX

Facility ID: 443669	Type: WELL	API Number: 123-42324	Status: XX	Insp. Status: XX
Facility ID: 443670	Type: WELL	API Number: 123-42325	Status: XX	Insp. Status: XX
Facility ID: 443671	Type: WELL	API Number: 123-42326	Status: XX	Insp. Status: XX
Facility ID: 443672	Type: WELL	API Number: 123-42327	Status: XX	Insp. Status: XX
Facility ID: 443673	Type: WELL	API Number: 123-42328	Status: XX	Insp. Status: XX
Facility ID: 443674	Type: WELL	API Number: 123-42329	Status: XX	Insp. Status: XX
Facility ID: 443675	Type: WELL	API Number: 123-42330	Status: XX	Insp. Status: XX
Facility ID: 443677	Type: WELL	API Number: 123-42331	Status: XX	Insp. Status: XX
Facility ID: 443679	Type: WELL	API Number: 123-42332	Status: XX	Insp. Status: XX
Facility ID: 443680	Type: WELL	API Number: 123-42333	Status: XX	Insp. Status: XX
Facility ID: 443683	Type: WELL	API Number: 123-42334	Status: XX	Insp. Status: XX
Facility ID: 443684	Type: WELL	API Number: 123-42335	Status: XX	Insp. Status: XX
Facility ID: 443685	Type: WELL	API Number: 123-42336	Status: XX	Insp. Status: XX
Facility ID: 443687	Type: WELL	API Number: 123-42337	Status: XX	Insp. Status: XX

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Inspector Name: Binschus, Chris

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

The subreport 'rptInsp13' could not be found at the

COGCC Comments

Comment	User	Date
Stormwater BMPs need to be installed prior to construction.	binschusc	12/23/2015
Stormwater BMPs need to be installed for the entire location by the end of business on 12/24/2015.		
Refer to attached photos in Doc.#682400169.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682400169	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3747818