

Construction Inspection



Photo 1. Photo taken from northeast location, facing West. Temporary BMP installed in center of photo while topsoil salvage is in process. Permanent BMPs will be installed upon completion of topsoil salvage.

Construction Inspection



Photo 2. Photo taken from northeast location, facing South. Temporary BMP installed in center of photo while topsoil salvage is in process. Permanent BMPs will be installed upon completion of topsoil salvage.

Construction Inspection



Photo 3. Photo taken from northwest location, facing South. Temporary BMP installed in center of photo while topsoil salvage is in process. Permanent BMPs will be installed upon completion of topsoil salvage.

Construction Inspection



Photo 4. Photo taken from southwest location, facing East. Temporary BMP installed in center of photo while topsoil salvage is in process. Permanent BMPs will be installed upon completion of topsoil salvage.

Construction Inspection



Photo 5. Photo taken from southwest location, facing East. Topsoil stockpile in center of photo.

Construction Inspection



Photo 6. Photo taken from western location, facing East. Topsoil salvage in process.