



Photo#1: Point where heavy Flow of SW enters Location at NW corner

September 3, 2016

Inspection Photos: Black Hills PA API#077-08427 Horseshoe Canyon



Photo#2: Erosion on Location

Inspection Photos: Black Hills PA API#077-08427 Horseshoe Canyon

September 3, 2016





Photo#3: Sediment build up.

Inspection Photos: Black Hills PA API#077-08427 Horseshoe Canyon

September 3, 2016



Photo#4: Stormwater still flowing and Pooling through Location.

Inspection Photos: Black Hills PA API#077-08427 Horseshoe Canyon

September 3, 2016





Photo#5: Rocked Drain has been installed since previous Inspection.

Inspection Photos: Black Hills PA API#077-08427 Horseshoe  
Canyon

September 3, 2016



Photo#6: Russian Thistle is establishing on Location.

Inspection Photos: Black Hills PA API#077-08427 Horseshoe  
Canyon

September 3, 2016





Photo#7: BMPs are containing Sediment; but erosion causing the Sediment migration needs to be controlled.

Inspection Photos: Black Hills PA API#077-08427 Horseshoe  
Canyon

September 3, 2016