

Interim Reclamation Inspection



Photo 1. Photo taken from eastern location, facing West. Topsoil brought into location. Interim reclamation IN-PROCESS.

Interim Reclamation Inspection



Photo 2. Photo taken of equipment (i.e., hay straw and hay buster) at location for reclamation work.

Interim Reclamation Inspection



Photo 3. Photo taken 12/1/16 by the Operator and emailed to COGCC staff. Location was graded, seeded, and straw mulched.

Interim Reclamation Inspection



Photo 4. Photo taken 12/1/16 by the Operator and emailed to COGCC staff. Location was graded, seeded, and straw mulched.

Interim Reclamation Inspection



Photo 5. Photo taken 12/1/16 by the Operator and emailed to COGCC staff. Location was graded, seeded, and straw mulched.