

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2017

Submitted Date:

03/17/2017

Document Number:

685302426

FIELD INSPECTION FORM

Loc ID 325215 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100264
 Name of Operator: XTO ENERGY INC
 Address: PO BOX 6501
 City: ENGLEWOOD State: CO Zip: 80155

Findings:

- 21 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Hixon, Logan	505-386-8018	logan_hixon@xtoenergy.com	SW EHS Tech
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	SW Inspection Reports
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214321	WELL	PR	05/01/1998	GW	067-05707	EARL JACK 1	PR

General Comment:

See link at end of report for path to downloadable pictures. Any open corrective actions from previous inspections are still applicable. This Inspection report contains corrective action and comment. See Lease Roads, Signs and Markers, Equipment, and Stormwater sections of report for additional comment.

Location			
Lease Road:			
Type	Access		
comment:	Dirt two track road off county road. Road requires maintenance as weather permits.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank labeling is below grade and not visible from outside edge of containment.		
Corrective Action:	Install signs and labels in a visible conspicuous place to comply with Rule 210.		Date: 05/17/2017
Type	WELLHEAD		
Comment:	Free standing framed sign at wellhead.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Glycol tank at wellhead has no NFPA label.		
Corrective Action:	Label tank to comply with Rule 210.d.(2).		Date: 05/17/2017
Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing.		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Post and hog wire fencing.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Gas meter run - Stock panel fencing.		
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 4		corrective date
Comment:	Deadmen markers have been broken and pushed over by cattle on location and need to be repaired.		
Corrective Action:			Date:

Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank and pump on spill prevention.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Riser and valve.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		
Comment:	Open top tank with steel mesh screen cover.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Tank is set in a square wooden walled pit.	
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 214321 Type: WELL API Number: 067-05707 Status: PR Insp. Status: PR

Producing Well

Comment: [PR - Electronic well file record review reflects last reported production as July 2016.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Fail	
		Culverts	Pass			

Comment: 50%-60% full 5 gallon bucket containing Ethylene Glycol and Methanol stored at wellhead with no spill prevention.

Corrective Action: Install or repair BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 04/17/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685302450	5 gallon bucket at the wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4101092
685302451	Chemical tank missing NFPA label.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4101093
685302452	Produced water tank with labels below grade and not visible.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4101094
685302453	Label on tank hatch not visible from outside tank containment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4101095
685302454	Rutted access road.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4101096