

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2017

Submitted Date:

05/30/2017

Document Number:

678800202

FIELD INSPECTION FORM

Loc ID 418026 Inspector Name: LEONARD, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426009	TANK BATTERY	AC	06/28/2010		-	SEKICH TANK BATTERY 14-19	SI

General Comment:

Inspection performed during onsite accident investigation. Tank battery was in process of re-construction at time of incident. 5 separators, 5 oil tanks and 5 water tanks had been removed. Construction was in process to commingle all wells into single battery at time of incident. Mountain View Fire Protection District and OSHA on site conducting investigations.

2017 Flowline NTO Inspection 100' Buffer

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Battery was under re-construction and not in use. Signs to be posted prior to reactivation of battery		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Chain link		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Flow Line	#		
Comment:	7 - 2" risers at separator. Flowlines from 13-19,14-19,12A-19 and 19-19 are commingled into 2 lines. GPS 40.210715/-104.932288.Shut in locked out tagged out		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Multiple run north of separator under construction		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	#		
Comment:	Currently under construction. All inlet valves closed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Single at separator		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Not hooked up		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	PBV FIBERGLASS		,

Comment: **Destroyed**

Corrective Action: _____ Date: _____

Paint

Condition _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				

Comment: _____

Corrective Action: _____ Date: _____

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		,

Comment: **Heavily damaged**

Corrective Action: _____ Date: _____

Paint

Condition _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				

Comment: _____

Corrective Action: _____ Date: _____

Venting:

Yes/No _____

Comment: _____

Corrective Action: _____ Date: _____

Flaring:

Type _____

Comment: _____

Corrective Action: _____ Date: _____

Inspected Facilities

Facility ID: 426009 Type: TANK API Number: - Status: AC Insp. Status: SI