

Inspection Photos – 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
3
API: 05-081-06434



Photo 1. Overview of location taken at entrance to location facing northeast.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
3
API: 05-081-06434



Photo 2. Pit at 40.889770, -108.299390



Photo 3. 2 – 2" steel riser, 2 – 1" insulated steel riser, 3 – 1" steel riser at wellhead

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
3
API: 05-081-06434



Photo 4. Flowlines to separator and motor for pump jack.



Photo 5. Landfarm at 40.88992, -108.29888.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
3
API: 05-081-06434



Photo 6. 2 – 2" steel risers at meter run. Unlabeled container in background.



Photo 7. Pit in tank battery at 40.889570, -108.298610

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
3
API: 05-081-06434



Photo 8. Flowlines and risers at tanks.



Photo 9. Flowlines and risers at tanks.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Powder Wash Federal 28-
3
API: 05-081-06434



Photo 10. Risers at horizontal separator.



Photo 11. Risers at vertical separator on right and horizontal separator on left.