



photo 1: Facing north toward the access road.



photo 2: Facing north toward the location.



photo 3: Facing north at the location. A wooden post remains at the center of the location.



photo 4: North side of the location facing south.



photo 5: There are signs of stormwater flowing off the north side of the location which can create erosion issues.



photo 6: Northeast side of the location facing southwest.



photo 7: East side of the location facing west.



photo 8: Facing east at the surrounding crop field.