

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2017

Submitted Date:

06/16/2017

Document Number:

687900023**FIELD INSPECTION FORM**
 Loc ID 308844 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@xtoenergy.com	
Fitzgerald, Edie	719-845-2108/719-859-1394	Edie_Fitzgerald@xtoenergy.com	Env. Tech, Raton Basin
Trujillo, Irwin	719-846-0272/719-859-2264	irwin_trujillo@xtoenergy.com	Sr. Env. Tech., Raton Basin
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283342	WELL	PR	01/12/2007	GW	071-08717	GOLDEN EAGLE 19-15	PR

General Comment:

2017 Flowline NTO Inspection
 Shadowing Operator Pressure Testing Team
 XTO Team : Lyndon L. Harrison, Joseph Garcia, Carl Vialpando

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 3" Tubing line riser at wellhead (37.15356/-104.92658) to discharge line.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 4" Casing line riser at wellhead (37.15356/-104.92658)		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 2" Fuel/Gas riser at Seperator (37.15355/-104.92671)		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 283342 Type: WELL API Number: 071-08717 Status: PR Insp. Status: PR

Flowline

#1	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 3" Material: Poly
 Variance: Yes Age: 10-15 Yrs Contents: Produced Water

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Material : Carbon Steel riser to Poly line. No Physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 10:50 am, P=30.5 psig, Time : 11:05 am, P=30.5 psig.

Corrective Action: Date:

#2	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 4" Material: Poly
 Variance: No Age: 10-15 Yrs Contents: Natural Gas

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Material : Carbon Steel riser to Poly line. No physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 11:11 am, P=2.0 psig, Time : 11:26 am, P=2.0 psig.

Corrective Action: Date:

#3	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Poly
 Variance: No Age: 10-15 Yrs Contents: Natural Gas

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: <u>Yes</u>		Test Result: <u>Pass</u>		Charted: <u>Yes</u>	
COGCC Rules(check all that apply)					
<input type="checkbox"/> 1101. Installation and Reclamation		<input checked="" type="checkbox"/> 1102. Operations, Maintenance, and Repair		<input type="checkbox"/> 1103. Abandonment	
<u>Comment:</u>		<div>Material : Carbon Steel riser to Poly line. No Physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 11:28 am, P=2.0 psig, Time : 11:43 am, P=2.0 psig.</div>			
Corrective Action:					Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401311635	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173846