

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/27/2017

Submitted Date:

06/28/2017

Document Number:

666803323**FIELD INSPECTION FORM**

Loc ID 421223 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421264	WELL	PR	12/27/2014	LO	045-20338	McLin A 13B-12-06-92	PR
421266	WELL	PR	01/05/2015	LO	045-20340	McLin A 34C-12-06-92	PR
421272	WELL	PR	01/05/2015	LO	045-20346	McLin A 23D-12-06-92	PR
421274	WELL	PR	06/15/2016	LO	045-20348	McLin A 34D-12-06-92	PR
421275	WELL	PR	01/18/2015	LO	045-20349	McLin A 34B-12-06-92	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift	# 5		
Comment:	39.536874/-107.617289		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	39.537054/-107.617816		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	39.537214/-107.617484		
Corrective Action:		Date:	
Type: Compressor	# 3		
Comment:	trailer mounted at separators		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	Not in use 12-2", Marked with paint, see photo		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	In use; 5-2" steel risers at wellhead, 19-2", 1-1" risers at separators, 2-2", 1-1" risers at tanks, 1-1" gas feed to ECB		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 10		
Comment:	39.537054/-107.617816		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	300 BBLS	STEEL AST		39.539221,-107.617049

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 421264 Type: WELL API Number: 045-20338 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 421266 Type: WELL API Number: 045-20340 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 421272 Type: WELL API Number: 045-20346 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 421274 Type: WELL API Number: 045-20348 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 421275 Type: WELL API Number: 045-20349 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: 2 ECB

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Berms	Pass					
Culverts	Pass					
Gravel	Pass					
		Gravel	Pass			
Ditches	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401323357	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183732
666803324	NT0	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183728
666803325	NT0 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183729
666803326	NT0 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183730
666803327	NT0 4	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183731