

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2017

Submitted Date:

06/28/2017

Document Number:

675103692**FIELD INSPECTION FORM**
 Loc ID 316200 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10200Name of Operator: PETROHUNTER OPERATING COMPANYAddress: 910 SIXTEENTH STREET SUITE 208City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256445	WELL	TA	06/04/2004	GW	103-09995	BUCKSKIN MESA UNIT 2571	EG

General Comment:

On location to perform 2017 flowline compliance and ensure well is TA - all openings bullplugged/needle valved. 1 - 2" steel flow line with 2 risers - Riser A capped/painted orange/ LOTO; Riser B capped/painted orange/LOTO

Inspected FacilitiesFacility ID: 256445 Type: WELL API Number: 103-09995 Status: TA Insp. Status: EG**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: On location to perform 2017 flowline compliance and ensure well is TA - all openings
bulplugged/needle valved. 1 - 2" steel flow line with 2 risers - Riser A capped/painted
orange/ LOTO; Riser B capped/painted orange/LOTO

Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401324756	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4184607