

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2017

Submitted Date:

07/13/2017

Document Number:

687400092**FIELD INSPECTION FORM**
 Loc ID 319856 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 27635Name of Operator: ENERGY SEARCH CO ADDBA ENERGY SEARCH COAddress: PO BOX 1896City: EDWARDS State: CO Zip: 81632**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments11 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		mike.hickey@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Rutter, Jenn		JRutter@adcogov.org	Unincrop. Adams County Inspections.
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201602	WELL	PR	02/19/2015	OW	001-07005	NORTH COLORADO BLVD 1	PR

**General Comment:**Within 1000' of dwelling.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Road is shared and maintained by great western battery.		
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: All signs have out of order emergency contact information. See Photos

Corrective Action: Install sign to comply with Rule 210.b.

Date: 08/14/2017

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil around wellhead and production tanks.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS	Date:	08/14/2017
Type	UNUSED EQUIPMENT		
Comment:	Unused tubing stored on location. See photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	10/13/2017
Type	TRASH		
Comment:	Trash stored inside of shed on location, see photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/14/2017
Type	DEBRIS		
Comment:	Debris is spread throughout location around separator and tank battery, see photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/14/2017
Type	WEEDS		
Comment:	Severely overgrown weeds through location, see photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	07/23/2017

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Privacy fence around location, is in disrepair.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Conventional unit		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment:	Produced water tank has no signage or placarding, see photos				
Corrective Action:	Install sign to comply with Rule 210.d.				Date: 08/14/2017

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Weeds have overgrown in and around berm. See Photo			
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.			Date: 07/23/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:	Rear water drain valve appears to be leaking. See Photos				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 08/14/2017

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Berms are overgrown with weeds, see photos			
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.			Date: 07/23/2017

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 201602 Type: WELL API Number: 001-07005 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Reords indicate shut in status as of 9/2014, no reporting since 2/2015.Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan.Date: 07/23/2017**COGCC Comments**

Comment	User	Date
Surface equipment, and location are in serious disrepair, well and battery are located in close proximity to several residences.	kraicha	07/13/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401341593	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4197428">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4197428</a>
687400093	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4197419">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4197419</a>