

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2017

Submitted Date:

08/04/2017

Document Number:

679100095**FIELD INSPECTION FORM**Loc ID 314871 Inspector Name: KUBECZKO, DAVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10539Name of Operator: SWEVCO - SABW LLCAddress: 1125 ESCALANTE DRCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dave Kubeczko		dave.kubeczko@state.co.us	
Steven Hale		shale@utahgascorp.com	

General Comment:

Date of Inspection: 06-08-17

Type of Inspection: Containment, Stormwater

Location Name: West Douglas Creek-62S103W 24NENW Pad; Dragon Trail Unit #1309 Well;

Location ID #: 314871

API #: 05-103-07458

Observed site reclamation and stormwater/erosion control on 06-08-17; no surface indication of pit; site is partially reclaimed with natural vegetation; no evidence of leaks or spills at wellhead; tank has secondary containment - no evidence of leaks or spills; stormwater/erosion controls are adequate - no indication of offsite migration of fluids or sediment from well pad; signage was still previous operator.

COGCC Comments

Comment	User	Date
	kubeczkd	07/11/2017