

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2017

Submitted Date:

08/07/2017

Document Number:

679100125**FIELD INSPECTION FORM**

Loc ID 334436	Inspector Name: KUBECZKO, DAVE	On-Site Inspection <input type="checkbox"/>	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
Lorne Prescott		lprescott@laramie-energy.com	
Dave Kubeczko		dave.kubeczko@state.co.us	

**General Comment:**

Date of Inspection: 05-9-17  
 Type of Inspection: Containment, Stormwater, Fracing  
 Location Name: Piceance 29-07 Pad; Numerous Wells  
 Form 2A #: 400694470  
 Location ID #: 334436  
 API #: Numerous Wells

Conducted inspection for site stormwater/erosion control and fracing/completion activities on 05-9-17; site control includes warning tape and sign-in; no evidence of leaks or spills at wellhead or on the well pad; stormwater/erosion controls are substantial and include straw wattles around entire well pad, straw wattles around topsoil pile, top soil pile and cut and fill slopes have been hydroseeded, cut and fill slopes have reclaim vegetation occurring, 12" to 24" or more complete perimeter compacted earthen berm with diversion trenches both inside and outside of pad and berm; containment includes additional berming around temporary frac tanks and liner beneath working area; access road dust being controlled with water application; wind socks; no odors detected during frac operations; location should be inspected once flowline tested and in production.

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401367897	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4219107">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4219107</a>