

- Sanchez 2 05-067-05345



Photo 1: Steel cable at left side of location entrance.

- Sanchez 2 05-067-05345



Photo 2: Open ended line.

- Sanchez 2 05-067-05345



Photo 3: Risers and casing vent at wellhead.

- Sanchez 2 05-067-05345



Photo 4: Location overview with weeds.

- Sanchez 2 05-067-05345



Photo 5: Leaking drain valve on left of frame and open ended riser below arrow.

- Sanchez 2 05-067-05345



Photo 6: Tank labeled empty.