

Inspection Photos
Location Name: Foster State 1
API: 05-081-07821



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Cuttings storage.

Inspection Photos
Location Name: Foster State 1
API: 05-081-07821



Photo 3. Cuttings storage.



Photo 4. Cuttings storage, debris visible on left.

Inspection Photos
Location Name: Foster State 1
API: 05-081-07821



Photo 5. Stormwater BMP- wattles- overwhelmed by sediment.