

Inspection Photos

10/05/2017

Operator: HRM RESOURCES II LLC - 10548

Location ID: 313925

Inspection Doc. Number: 682502644

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the access road entrance. Photo shows cattle guard equipment has been removed and filled.

Inspection Photos
Operator: HRM RESOURCES II LLC - 10548
Location ID: 313925



Photo 2: Photo taken from the access road, north of the location. Photo shows portion of the North/South access road requiring reclamation. The contractor on site had stated topsoil had been brought in to fill the road.



Photo 3: Photo taken from the access road, north of the location. Photo shows portion of the East/west portion of the road not being reclaimed. The contractor on site had stated that any gravel or road base removed from the access road, had been placed on this section of the road for the surface owner.



Photo 4: Photo taken from the access road, north of the location. Photo shows topsoil had been brought in for the road. Note: COGCC reclamation rules require access roads to be cross ripped to a depth of 18 inches. After conversations with the contractor on site at time of inspection, it was indicated that the required compaction alleviation had not yet been conducted, and that there was no schedule to perform the work.

Inspection Photos
Operator: HRM RESOURCES II LLC - 10548
Location ID: 313925



Photo 5: Photo taken from the southwest end of the location, facing north. Photo shows the well location. Straw wattle stormwater BMP on the west end of the location appear to be in proper functioning condition.



Photo 6: Photo taken from the southwest end of the location, facing east. Photo shows the well location. Well location had been seeded spring 2017. Though some areas may require additional work, large areas of the location appear to be progressing towards reclamation requirements. Continue to monitor and manage well location and perform reclamation as needed.



Photo 7: Photo taken from the location, facing northeast. Photo shows equipment on site. Contractor indicated backhoe had been used for all dirt work conducted on access road.