



Photo 1. View from the northwestern corner of the project area facing center. Black and blue tanks in the background do not appear to be in use for this well.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward. Revegetation in the outer portions of the project disturbance is progressing with grasses and forbs such as western wheatgrass (*Pascopyrum smithii*), giant squirreltail (*Elymus multisetus*), and penstemon (*Penstemon* sp.).



Photo 3. View of the western portion of the project area from the northwestern corner facing southward.



Photo 4. View of area in the southwestern portion of the project area with erosive scouring. This channeling pattern is evident before construction of the well pad and significant erosion does not appear to be occurring at this time. However, these sensitive areas should be monitored and stormwater controls installed if erosion worsens, as concentrated runoff from the well pad could increase the rate of erosion.





Photo 5. View of the eastern portion of the project area from the well pad entrance facing southward. Pipes and jersey barriers do not appear to be in use.



Photo 6. View of Canada thistles (*Cirsium arvense*) within the northeastern cut-slope.