

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2017

Submitted Date:

11/06/2017

Document Number:

680402081

**FIELD INSPECTION FORM**

Loc ID 311866 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 56680  
Name of Operator: MERRION OIL & GAS CORP  
Address: 610 REILLY AVENUE  
City: FARMINGTON State: NM Zip: 87401

**Findings:**

- 20 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Philana	(505) 324-5300	pthompson@merrion.bz	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232862	WELL	PR	03/19/1993	GW	113-06051	COCKLEBUR DRAW UNIT 1	SI

**General Comment:**

*(This area is intentionally left blank for general comments.)*

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road with washed out and pothole sections.		
Corrective ActionL	Repair and maintain lease road.	Date:	12/06/2017
Type	Main		
comment:	BLM surface		
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign for Cocklebur Draw Metering Facility		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign has wrong API#. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	01/03/2018
Type	TANK LABELS/PLACARDS		
Comment:	Maintain labels on chemical tanks.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Keep weeds clear of fired equipment and tank berms. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/17/2017
Type	TRASH		
Comment:	Trash and junk removed as required from previous inspection Doc#680401073 and submitted with FIRR Doc#401176799 on 1/3/2017. See attached pitures. Continue to clear unused equipment (flanges, pipes, wires, etc.)		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Reboiler water line broken and disconnected from tank. See attached photos.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	12/06/2017
Type	UNUSED EQUIPMENT		
Comment:	Dehydrator and Glycol reboiler.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/08/2017
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			

Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	WELLHEAD				
Comment:	Panel fence around wellhead				
Corrective Action:				Date:	
Type	OTHER				
Comment:	Pipe barricade around dehydrator				
Corrective Action:				Date:	
Type	SEPARATOR				
Comment:	Pipe barricade around separators				
Corrective Action:				Date:	
<b>Equipment:</b>					
Type: Horizontal Heated Separator	# 2			corrective date	
Comment:					
Corrective Action:				Date:	
Type: Flow Line	# 4				
Comment:	Observed multiple abandoned risers not marked/locked out/tagged out on W side of pad (2" & 3" ~ 37.968736, -108.521789) & (2" ~ 37.968581, -108.521869). Flowline risers not LO/TO or marked are considered unused equipment				
Corrective Action:	Comply with Rule 603.f .			Date: <u>12/08/2017</u>	
Type: Dehydrator	# 1				
Comment:	with glycol reboiler				
Corrective Action:				Date:	
Type: Deadman # & Marked	# 2				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 3				
Comment:					
Corrective Action:				Date:	
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER					
Comment:	All chemical drums have been removed or placed inside secondary containments as required from previous inspection Doc#680401073 and submitted with FIRR Doc#401176799 on 1/3/2017. See attached pictures.				
Corrective Action:				Date:	
<b>Paint</b>					

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.968643,-108.521893
Comment: <a href="#">Glycol reboiler water tank. Unused equipment with disconnected line.</a>					
Corrective Action: <a href="#">Comply with Rule 603.f .</a>					
Date: <u>12/08/2017</u>					

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:				
Corrective Action: <a href="#">Maintain berms or remove tank.</a>				Date: <u>12/08/2017</u>

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		37.968255,-108.521414
Comment:					
Corrective Action:					
Date:					

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Tank berms have been repaired as required from previous inspection Doc#680401073 and submitted with FIRR Doc#401176799 on 1/3/2017. See attached pictures.</a>				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 232862 Type: WELL API Number: 113-06051 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well shut in Jan 2016.  
MIT due by Jan 2018.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	Secondary containment around chemical drums

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680402084	Inspection photos 10/23/2017	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295492">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4295492</a>