



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.





Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*), western wheatgrass (*Pascopyrum smithii*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).





Photo 4. View of erosional channel and pipe debris within the western portion of the project area.



Photo 5. View of erosional rilling in the western portion of the project area.



Photo 6. View of erosional channels near the entrance to the well pad.