

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/05/2018

Submitted Date:

01/05/2018

Document Number:

674902014

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
378716 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69805
Name of Operator: PETROX RESOURCES INC
Address: P O BOX 2600
City: MEEKER State: CO Zip: 81641

Findings:

- 8 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Nystrom, Dusty	505-330-1328	nystrw@yahoo.com	All Inspections
St John, William (Cal)		cal.stjohn@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Clark, Mike	970-878-5594	mike.petroxcbm@gmail.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301884	WELL	PR	07/01/2013	GW	007-06275	LARK 33-5 21-2	EI
444385	WELL	PR	12/01/2016	LO	007-06323	Lark 33-5 21-4	EI

General Comment:

On January 5, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Petrox Resources Inc. Lark 33-5 #21-4. This field inspection resulted from a complaint regarding a release on the location. For the most recent field inspection report of this facility, please refer to document #674901232.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign located near each well head.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact number used to attempt to notify operator of release at separator. Number listed on location signs, 970-878-5595, has been disconnected. Petrox representative used a marker to temporarily correct the signs on this location during this inspection. Actual operator contact phone number is 970-878-5594.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 02/05/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Produced Water	Separator		
Comment:	Hammer union on water line observed dripping during this inspection. Ice and fluids within separator housing. Petrox representative notified of release. Connection was tightened up, and release was stopped.		
Corrective Action:	Securely fasten all valves , pipes, and fitting to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condtion per Rule 605.d.		Date: 01/06/2018
Produced Water	WELLHEAD		
Comment:	COGCC staff notified of release near well head 1/4/18. Horizontal tank, attached to the well, had been removed by the time of this inspection.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.		Date: 02/05/2018
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 301884 Type: WELL API Number: 007-06275 Status: PR Insp. Status: EI

Facility ID: 444385 Type: WELL API Number: 007-06323 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Pass	Compaction	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On January 5, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Petrox Resources Inc. Lark 33-5 #21-4. This field inspection resulted from a complaint regarding a release on the location. Imaged submitted to the COGCC showed a horizontal tank attached to the well head with fluids around it and mist coming from the top of the tank. For the most recent field inspection report of this facility, please refer to document #674901232.</p> <p>The horizontal tank had been removed, reportedly earlier on 1/5/18, by the time of this field inspection. A mark from the skid was present where the tank sat. Damp soil was present surrounding the area where the tank was located. Dusty Nystrom, Petrox representative, collected a soil sample of the impacted area. 5 - 4 oz. glass sample jars and two Ziploc bags were filled with the damp soil from 37.08489/-107.40588 for analysis at Green Analytical Laboratory.</p> <p>The contact information on the well signs was temporarily corrected with a marker, when the operator was told that the listed number had been disconnected.</p> <p>During this inspection a leaking hammer union in the separator shack for the #21-4 was observed. The operator was notified and the connection was tightened up, stopping the release.</p>	hughesj	01/05/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674902015	Inspection Photos 1/5/18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4342566