

**Inspection Photo  
McPherson A-3  
API# 045-14477  
Inspection # 689301178**



**Location Photo #1**



**Location Photo #2, Stained material in tank containment**

**Inspection Photo  
McPherson A-3  
API# 045-14477  
Inspection # 689301178**



**Location Photo #3, Stained material in tank containment**

**Location Photo #4, Stained material in tank containment**

**Inspection Photo  
McPherson A-3  
API# 045-14477  
Inspection # 689301178**



**Location Photo #5, Stained material in tank containment**



**Location Photo #6, Erosion along West side of access road**

**Inspection Photo  
McPherson A-3  
API# 045-14477  
Inspection # 689301178**



**Location Photo #7, Erosion along West side of access road**

**Location Photo #8, Erosion along West side of access road**