

Inspection Photos 5/22 – 5/31/18 (J. MacLaren)
Location: Hyndrex Resources Flowline System
Spill ID #455229



View of first responders to natural gas/ fluid release (looking east from intersection of Hwy 85/ WCR 18.5 on 5/22/18)



View (looking SE) of impacted area where flowline failed resulting in release (from WCR 18.5)

Inspection Photos 5/22 – 5/31/18 (J. MacLaren)
Location: Hyndrex Resources Flowline System
Spill ID #455229



**View of pooled fluid in agricultural field (marked/ staked)
where flowline failed resulting in release (looking SE)**



Close up view of pooled fluids (primarily water) at surface

Inspection Photos 5/22 – 5/31/18 (J. MacLaren)
Location: Hyndrex Resources Flowline System
Spill ID #455229



Photo taken 5/30/18 of excavation exposing (2) Hyndrex Resources 3" fiberglass flowlines; initial (failed) repair can be seen on Northern most flowline



Photo of failed repair completed by contractor (no longer working on this project); Fiberglass coupler improperly installed, no adhesive used to complete connection

Inspection Photos 5/22 – 5/31/18 (J. MacLaren)
Location: Hyndrex Resources Flowline System
Spill ID #455229



View of follow-up repair completed to the damaged section of flowline; HDPE pipe section replaces damaged section of flowline. GPS marker ball placed in area of repair



Closer view of the transition between existing fiberglass flowline and replacement section of (HDPE/ Poly) pipe