

**Inspection Photos**  
**Location Name: Lilli Unit #16-6**  
**Location ID: 326799**



**Photo 1: Wellhead**



**Photo 2: Location**



**Inspection Photos**  
**Location Name: Lilli Unit #16-6**  
**Location ID: 326799**



**Photo from prior inspection for comparison**



**Photo 3: Stormwater erosion S of wellhead**



**Inspection Photos**  
**Location Name: Lilli Unit #16-6**  
**Location ID: 326799**



**Photo 4: No capacity at produced water vault**