

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/05/2018

Submitted Date:

07/05/2018

Document Number:

691400660**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 307326 Beardslee, Tom 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217459	WELL	PR	12/01/2017	GW	071-06236	BURRO FED 11-18	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Location sign adequate.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:	Adequate		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Prime Mover	# 1		
Comment:	Gas powered		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	All have makers		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	217459	Type:	WELL	API Number:	071-06236	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	
BradenHead									
Comment:		Not plumbed to surface							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: Lat: 37.176810Long: -104.719270Reference Point: SEOther: Length: 100Width: 40**Lining:**Liner Type: PlasticLiner Condition: Inadequate

Comment:

Multiple holes in pit liner on pit wall and on top edge of liner. Water level is well below holes in liner and well is not producing water at the time of inspection.

Corrective Action

Lack of pit liner or pit liner compromised (Rule 904). IMMEDIATE NOTIFICATION TO THE OPERATOR Reduce fluid level in pit, contact COGCC EPS staff for directives.

Date: 07/19/2018c**Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment:

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment:

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment:

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	263629	1325842	<input type="text"/>
	263629	1325842	<input type="text"/>

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691400661	LOC PICS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515173