



Photo 1. View of the project area from the southeastern corner of the working area facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing within grasses such as western wheatgrass (*Pascopyrum smithii*) and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the western portion of the project area from the southwestern corner facing northward. Russian knapweeds (*Rhaponticum repens*) are growing in the foreground on berm.



Photo 4. View of Russian knapweeds within the southeastern portion of the project area. Project area is defined as all areas disturbed for the project. Aerial imagery indicates knapweed infestation is within project area. Additional knapweed is outside of the project area, so monitoring and subsequent treatments will be needed.



Photo 5. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 6. View of unmarked rig anchor within the project area.