



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Very little vegetative cover observed here.



Photo 3. View of erosional channels approximately 1 foot wide and deep in the western portion of the project area.



Photo 4. View of more erosional channels in the western project area.



Photo 5. View of the eastern portion of the project area from the northeastern corner facing southward.