

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2018

Submitted Date:

07/16/2018

Document Number:

689801369**FIELD INSPECTION FORM**Loc ID 312868 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|----------------------------------|---------|
| Ikenouye, Teri | | teri.ikenouye@state.co.us | |
| Evans, Clay | | antlerenergy@yahoo.com | |
| | | dnr_cogccengineering@state.co.us | |
| Leonard, Mike | | mike.leonard@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 222669 | WELL | PR | 01/29/2001 | GW | 081-06029 | BAGGS LAND & CATTLE 1 | PR |

General Comment:

Routine FIU follow up inspection.

Follow up to inspection from 11/20/2017 document number 689800577.

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers. One tank remains unlabeled. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 02/13/2015 |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | 1 - 2" steel riser not marked for abandonment or LOTO at compressor. Flowline risers not LO/TO or marked are considered unused equipment. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 07/17/2018 |

Overall Good: ☐

| | | | | |
|--|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: _____ | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |

| | | | |
|---------------------------------|----------------------|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # | | |
| Comment: | | Date: | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heater Treater | # 1 | | |
| Comment: | 40.99942, -107.70524 | Date: | |
| Corrective Action: | | Date: | |
| Type: Compressor | # 1 | | |
| Comment: | 40.99918, -107.70539 | Date: | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|-------|----------|-----------|---------|--------|
| CONDENSATE | 1 | 200 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | Date: | | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | | | Adequate |
| Comment: | | | | |
| Corrective Action: | Date: | | | |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|-------|----------|-----------|---------|-----------------------|
| | 1 | | STEEL AST | | 40.999280,-107.705410 |
| Comment: | | | | | |
| Corrective Action: | Date: | | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | | | Adequate |
| Comment: | | | | |
| Corrective Action: | Date: | | | |

Inspected FacilitiesFacility ID: 222669 Type: WELL API Number: 081-06029 Status: PR Insp. Status: PR**Producing Well**Comment: Produced volumes are required to be reported accurately from the wellhead meter every month, and the form 7 reporting does not reflect that accurate measurement.Corrective Action: Submit required Form 7(s) to COGCC.
Please contact Teri Ikenouye (production supervisor) to discuss reporting parameters.Date: 08/16/2018

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
| | 260483 | 200017325 | |

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| Follow up to inspection from 11/20/2017 document number 689800577. Tank labels remain outstanding from that report and this report contains additional corrective actions. | waldrone | 07/16/2018 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 689801375 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4524950 |